

## Re: USB 2.0 Hubs

**Source:**

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2004-07/5126.html>

---

**From:** Charlie (*Nobody\_at\_Nowhere.com*)

**Date:** 07/31/04

Date: Sat, 31 Jul 2004 00:10:08 GMT

Great Call ! I checked where the USB connector attached to the front panel and it was one pin off. It was hiding behind another plug and very hard to see. I had been focusing on the stub on the motherboard. Every thing works great. Thanks.

"Nathan McNulty" <nospam@msn.com> wrote in message news:ehmxyZodEHA.3864@TK2MSFTNGP10.phx.gbl...

> *Two possibilities that I can think of as well:*

> *1) Make sure that they are all on HiSpeed in the BIOS. It is possible*

> *to have half USB 1.1 and half USB 2.0 (but that would be an odd option*  
> *in the BIOS and definetly not a default).*

> *2) The pins are set up wrong on the motherboard for the USB connector.*

> *This would only pertain to the front panel USB connectors. If you have 2*  
> *slots on the front and one works, but the other doesn't, check and make*  
> *sure both are connected the same.*

>

> -----

> *Nathan McNulty*

>

>

> *R. C. White wrote:*

> > *Hi, Charlie.*

> >

> > *Congratulations on your new mobo/PC! My new EPoX 8KDA3+ also supports 8*

> > *USB 2.0 ports. Four are on the backplane and came already wired up.*

> > *The other four are supported by two sets of pin headers (2 ports each)*

> > *on the mobo, to which I had to attach plugs leading to the 2 ports on a*

> > *backplane bracket and 2 ports on the front of my computer case. (My old*

> > *mobo came with only USB 1.1, so I had added a 4-port USB 2.0 PCI card to*

> > *it; since I didn't want to leave an empty slot in my new backplane for*

> > *air and dust-bunnies to come in, I've plugged in that card, too, so I*

> > *now have 12 USB 2.0 ports. Woohoo!*

> >

> > *My USB devices are a mixture of 2.0 and 1.1. My thumb drive is 1.1 and*

> > *I haven't plugged it in since I upgraded the mobo. Let's see... Yes, a*

> > *series of messages appeared in my Notification Area (SysTray) and now my*

> > *"new drive" is installed. I've moved it to several other ports and they*

> > *all work smoothly; the thumb always shows up as "Removable drive (G:)"*.

> > *My SD card reader (2.0) is recognized in either the back or front slot*  
> > *with no complaints.*  
> >  
> > *I don't know what might be causing your port to be seen as low speed,*  
> > *but maybe my comments can help you narrow it down. What make and model*  
> > *is your mobo? Maybe some ports are low-speed, but that seems unlikely;*  
> > *if some are high-speed, all should be high-speed.*  
> >  
> > *RC*