

Re: USB 2 PCI board problems

Source:

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2005-06/msg01530.html>

- *From:* "R. McCarty" <PcEngWork-NoSpam @xxxxxxxxxxxxxxxx>
 - *Date:* Sat, 25 Jun 2005 07:09:42 -0400
-

Which PCI slot did you install the card into ? Numbering schemes vary but usually PCI Slot #1 is designated as the one adjacent to the AGP slot. XP can handle IRQ sharing and your motherboard probably has an APIC controller that raises IRQ mapping to #23. I'm a little out of touch with the newer boards, but on previous MBs Slots #2 & #5 have independent IRQ mappings.

Are you continuing to use the motherboard based USB channels or just using your new USB2.0 ? You may want to disable the motherboard USB channels (Via BIOS).

"F" <news@xxxxxxxxxxxxxxxxxxxx> wrote in message [news:42bd3836\\$0\\$41891\\$ed2619ec@xx](mailto:news:42bd3836$0$41891$ed2619ec@xx)

- > Ever since I installed a USB 2 PCI board (NEC chipset) on my Asus AV266-E
- > motherboard running Win XP Pro SP2 I've had random lockups. Sometimes when
- > booting up, sometimes when shutting down, other times when opening a
- > folder or when inserting a memory card into a USB 2 card reader.
- >
- > Any suggestions by way of a solution? I have reloaded the Microsoft USB
- > 2.0 driver and have installed the latest Via update.
- >
- > --
- > F
- >
- > (Beware of spam trap - remove the negative)

-
- *Follow-Ups:*
 - ◆ **[Re: USB 2 PCI board problems](#)**
 - ◇ *From:* F
 - Prev by Date: **[USB Problems](#)**
 - Next by Date: **[Re: USB 2 PCI board problems](#)**
 - Previous by thread: **[USB Problems](#)**

Re: USB 2 PCI board problems

- Next by thread: ***Re: USB 2 PCI board problems***
- Index(es):
 - ◆ ***Date***
 - ◆ ***Thread***