Re: Hardware Problem?

Source:
http://www.tech−archive.net/Archive/WinXP/microsoft.public.windowsxp.basics/2007−07/msg00034.html

- *From*: "Curt Christianson" <curtchristnsn@xxxxxxxxxxxxxxx>
- *Date*: Sun, 1 Jul 2007 10:49:06 −0500

Just read your post about replacing the mobo−−congratulations!

−−
HTH,
Curt

Windows Support Center
www.aumha.org
Practically Nerded,...
http://dundats.mvps.org/Index.htm

"Earl Partridge" <earlpNG@xxxxxxxxxxx> wrote in message
news:kSPhi.2667$Od7.1470@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx
| Must be my lucky day. Yep, the machine has been tried from several
| different
| outlets, two different homes... etc. But my luck is that I happened to
| have another
| old computer and its motherboard has the same CPU socket. I replaced the
MB
| in the non functioning machine... and that fixed it.
| Earl
|
| "Harry Ohrn" <harry−−−@xxxxxxxxxx> wrote in message
| news:OnsNdN$uHHA.1204@xxxxxxxxxxxxxxxxxxxxxx
| >I once had a case where the reset switch was faulty and essentially stuck
| >on so that when the computer was powered up it was as thought the reset
| >switch was continuously depressed. Try unplugging the reset switch from
the
| >mother board or both reset and power switch and then simply short the 2
| >pins which the power switch plugs into. You use a small screw driver to
| >short the pins by simply allowing the two pins to briefly be connected.
| >
| > −−
| >
| >
| > Harry Ohrn MS MVP [Shell\User]
| > www.webtree.ca/windowsxp
| >

| >
| > "Earl Partridge" <earlpNG@xxxxxxxxxxx> wrote in message
| > news:gYNhi.2671$zA4.1371@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx
| >> Windows XP Home
| >> This is apparently a hardware problem but thought there'd be some
pretty
| >> good
| >> ideas of the problem here. No power, no lights, no fan action, no HD
| >> noise... nothing at all.
| >> Checked swith for continuity − ok
| >> Checked power supply in another computer − ok
| >> Tried another power supply in this computer − still nothing.
| >>
| >> Suspect bad component on motherboard. Is there anything specific I
could
| >> look
| >> for on the botherboard? Perhaps replacing the motherboard would be
best
| >> idea?
| >>
| >> Motherboard is K7 − M810XLM, Socket 462
| >>
| >> Earl
| >>
| >>
| >
| >
|
|

.