

# Remote Install Wyse 9150SE

---

*Source:*

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.embedded/2006-04/msg00015.html>

---

- *From:* "Richard Morey" <[rwmorey71@xxxxxxxxxxxx](mailto:rwmorey71@xxxxxxxxxxxx)>
  - *Date:* Mon, 3 Apr 2006 09:59:30 -0400
- 

Hi..

I have a single Wyse 9150SE on my network and I screwed it up.. So I wanted to reinstall the image to it. It runs Windows XPe. I downloaded the image file from the Wyse website but their "simple imager" utility is ANYTHING but simple --- it requires two or three prerequisites and the one page help file is confusing. I finally got that working I thought but could not get the device to find all the files it needed to reimage it.

I then tried to install the Rapport 4.4.1 software that Wyse offers but I couldn't even get that installed.

I called Wyse and they suggested I send the unit back to them for reimaging. This unit is not essential --- its something I'm playing with to learn more about XPe and building ActiveX controls to run on that O/S so I forsee needing or wanting to reimage the unit with some regularity.

I have installed the Remote Installation service on my Windows 2003 Server but the initial setup is looking for an install directory. The only thing I have is a file from Wyse with a I2D extension. Can I use this file with the Remote Install service? If not can I some how extract / convert / etc. this file into something I can use?

Thanks

Rich

---

Richard Morey  
[rmorey@xxxxxxxxxxxxxxxxxxxx](mailto:rmorey@xxxxxxxxxxxxxxxxxxxx)

Sea Spray Software, Inc.  
55 Newtown Lane  
East Hampton, NY 11937  
(631)329-1233

