

# KB885222

---

*Source:*

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.general/2005-04/msg15588.html>

---

- *From:* "Paul" <[goneouttolunch@xxxxxxxx](mailto:goneouttolunch@xxxxxxxx)>
  - *Date:* Wed, 27 Apr 2005 19:49:19 +1200
- 

Hi all this fix.

Performance of 1394 devices may decrease after you install Windows XP Service Pack 2.

I see it says this, on the MS site

## CAUSE

This problem occurs if you connect a 1394a or 1394b FireWire device to a 1394b port. This problem occurs because Windows XP SP2 changes 1394b ports to S100 speed when you upgrade.

I take it by the MS site SP2 only affects 1394b not 1394a??

If I have 1394a I wouldnt need this fix/patch would I??

Or does it apply to BOTH 1394a and 1394b?

---

• *Follow-Ups:*

◆ **Re: KB885222**

◇ *From:* Rick \"Nutcse\" Rogers

- Prev by Date: **Scheduled Tasks**
- Next by Date: **error 623**
- Previous by thread: **Generic Host Process for Win32 Error Message**
- Next by thread: **Re: KB885222**

- Index(es):

- ◆ *Date*

- ◆ *Thread*