

Re: Power Surge on USB port

Source:

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.general/2005-05/msg10264.html>

- *From:* "Steve N." <me@xxxxxxxx>
 - *Date:* Tue, 17 May 2005 23:38:28 GMT
-

Chuck wrote:

Sounds like the Laptops internal power supply regulation leaves a bit to be desired.
(It may be getting ready to quit.) One of my daughters had a laptop that started acting in a similar manner, then died with a fried internal power supply.

I agree with Richard and Chuck, there is a possible problem with the power supply and/or the charging/regulator circuit on the motherboard and/or the battery and/or the USB circuits on the motherboard. Contact Acer for tech support. This should not be happening.

Steve

"Richard Urban" <richardurbanREMOVETHIS@xxxxxxxxxxxxxx> wrote in message news:emvbqzyWFHA.2256@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxx

You want it to just go away? You are not concerned about the warning of possible hardware damage? I think I would contact Acer about this if I were in your position!

--
Regards,

Richard Urban

aka Crusty (-: Old B@stard :-)

