

## Highpoint controller and KB822603

**Source:**

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2004-05/1392.html>

---

*anonymous\_at\_discussions.microsoft.com*

**Date:** 05/10/04

Date: Sun, 9 May 2004 19:36:33 -0700

Strange, I have the same highpoint controller with a RAID0 and the OS (XP) on IDE1 setup, except my MoBo is an Abit kr7a-133r (slot A). I don't have any problems with the hotfix and USB.

What Highpoint 374 driver are you using? The latest for that board is ver 1.23

You might try posting your question in Abit's user forum.

<http://forum.abit-usa.com/index.php?s=86435a8928b3f81356da89b6321e03ed>

>-----Original Message-----

>Hey folks,

>

> Not sure if anyone knows a fix for this one, but I

imagine it is

>something Highpoint and Microsoft have to sort out. I have an Abit IT7

>motherboard that has an onboard Highpoint HPT374 RAID controller. I have two

>disks set-up as RAID0 on this controller for personal files and (thankfully)

>a disk on IDE1 for the OS. The Microsoft hotfix for USB power management

>(http://support.microsoft.com/?kbid=822603) messes up the Highpoint

>controller's power management. Resuming from suspend to RAM (S3 sleep state)

>with this hotfix installed wipes out my RAID0 disks and I am forced to

>reboot. If I uninstall the hotfix, I no longer has the problems with my

>HPT374 controller. I sure as hell hope this gets fixed before this hotfix

>gets rolled into SP2 and there will be no way for me to

remove it.

>

>*Dave*

>

>--

>

>\_\_\_\_\_

>*Remove "yourclothes" to reply directly.*

>

>

>.

>

>