

SYSTEM RUNNING/BOOTING SLOW...

Source:

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2004-07/4718.html>

From: RAHUL GHOSH (*rahul_deb2002_at_hotmail.com*)

Date: 07/28/04

Date: Wed, 28 Jul 2004 13:09:07 -0700

(1)I'm having 2 HardDisks & 2 CDdrives in my system.. My HDD's RPM may not be same, i'm not very sure..But how does it affect system boot time if RPM of both drives are dissimilar?? Because if the RAMs doesn't match(in case u r having 2 RAMs in the system), then the system will not boot..Similarly if the HDdrives' RPM are not similar then how will it affect the system—will it ever boot or boot slow???

(2)Finally please tell me the correct rule to connect 2HDDs & 2CD drives with the IDE ports of the motherboard in terms of primary & secondary master/slave ...I mean to say how should one connect the 2 harddisks & 2 CD drives with the IDE ports of motherboard in terms of primary & secondary master/slave??? whether the HDDs should be connected as primary master & 2ndary master or as primary master & primary slave???

(3)Also please tell me win-XP works better on which—FAT32 or NTFS ???

please help

Regards,

Rahul..