

## Re: External firewire CF card reader not recognised

**Source:**

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2004-10/0261.html>

---

**From:** Jim Macklin (*p51mustang@threeX12*)

**Date:** 10/02/04

Date: Fri, 1 Oct 2004 19:11:27 -0500

See if you can find any firmware updates for the card reader. Delete the entire list of firewire devices and ports. See if the Audigy card has any limitations, firmware updates.

Which port are you using?

--  
The people think the Constitution protects their rights;  
But government sees it as an obstacle to be overcome.  
"Wesley" <Wesley@discussions.microsoft.com> wrote in message  
news:4D654082-A85E-4766-88E2-3E8454F2A002@microsoft.com...  
| Thanks Jim,  
|  
| After rebooting OS would recognise card reader as a type  
II CF reader,  
| however there was yellow exclamation mark next to it,  
after few seconds  
| "SBP2 Compliant  
| IEEE 1394 device" driver loads and that's it.  
|  
| Would you have any other suggestions?  
|  
| I forgot to mention my machine has two firewire ports, one  
on the  
| motherboard the other with Audigy Platinum.  
|  
| Weird thing both ports are listed in Dev Manager as OHCI  
Compliant IEEE 1394  
| Host Controller with Microsoft drivers loaded.  
|  
| Any other suggestions, on how to fix this problem?  
|  
| "Jim Macklin" wrote:  
|  
| > Delete the card reader ["SBP2 Compliant | IEEE 1394  
| > devices"] in device manager and it should be redetected  
| > properly when you reboot. Unplug the card reader when  
you  
| > do this and plug it in after the reboot.  
| >  
| >

microsoft.public.windowsxp.hardware: Re: External firewire CF card reader not recognised

```
| > --
| > The people think the Constitution protects their rights;
| > But government sees it as an obstacle to be overcome.
| >
| >
| > "Wesley" <Wesley@discussions.microsoft.com> wrote in
message
| >
news:DF79D4B2-6DB9-4F51-A115-04D60A62BBAD@microsoft.com...
| > | Hi,
| > |
| > | After installing firewire drivers for Epson scanner my
| > | firewire CF card
| > | reader doesn't show as a removable drive in windows
| > | explorer anymore.
| > | After connecting card reader I can see in the device
| > | manager "SBP2 Compliant
| > | IEEE 1394 devices" but not a removable drive. Driver
| > | details are -
| > | sbp2port.sys - file version 5.1.2600.2180
| > | (xpsp_sp2_rtm.040803-2158)
| > | I have noticed that after loading firewire drivers for
| > | sony digital camera,
| > | I have lost my epson scanner, but after reinstalling
| > | drivers both camera and
| > | scanner are working fine.
| > | I do not have drivers for my firewire card reader, but
I
| > understand those
| > | drivers are included in OS.
| > | I am running Windows XP SP2, Athlon 3000XP, 1G RAM,
2x80G
| > SATA RAID
| > |
| > | Thanks for any hints
| > |
| > | Regards
| > |
| > | Wesley
| >
| >
| >
```