

RE: Can't get USB hubs to work...

Source:

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2004-10/3595.html>

From: BAR (*BAR_at_discussions.microsoft.com*)

Date: 10/29/04

Date: Thu, 28 Oct 2004 23:12:01 -0700

You may need to install a USB2 driver separately. Check your motherboard Cd for a specific USB2 driver for the onboard chipset.

Belkin's Manual indicates that no drivers are necessary.

"billjup" wrote:

- > *I have a Belkin Hi-Speed USB 2.0 7-port hub with power and can't get it*
- > *installed. When I plug into any of the USB 2.0 ports on my system, it detects*
- > *it and lists it in Device Mgr as a "USB Device" with a yellow exclamation*
- > *point. The add new hardware wizard launches and I follow through it and it*
- > *doesn't find a driver, despite having my WinXP Pro disk in the drive and*
- > *having WinXP SP2 installed.*
- >
- > *I've also tried 2 different generic 4-port hubs with no power, and they*
- > *produce the same results.*
- >
- > *I have 4-5 USB devices that work perfectly fine with this machine (printer,*
- > *mouse, camera, smartcard reader, video camera).*
- >
- > *Any ideas?*
- > --
- > *Thanks in advance*
- >
- > *Bill*