

## Re: DVD-RW after upgrade to AMD64

---

*Source:*

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2005-06/msg01052.html>

---

- From: "KayZer Soze" <[thesuspects@xxxxxxxxxxxxxxxx](mailto:thesuspects@xxxxxxxxxxxxxxxx)>
  - Date: Thu, 16 Jun 2005 16:32:19 -0300
- 

A friend told me to try to changedriver controller properties, to PIO Mode.  
What do you think about?

"NoNoBadDog!" <[no\\_@xxxxxxxxxxxxxxxx](mailto:no_@xxxxxxxxxxxxxxxx)> wrote in message  
[news:O1DIQdjcFHA.2436@xxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:news:O1DIQdjcFHA.2436@xxxxxxxxxxxxxxxxxxxxxxxxxxxx)  
>  
> "Flavio Borup" <[fborup@xxxxxxxxxxxx](mailto:fborup@xxxxxxxxxxxx)> wrote in message  
> [news:u1bMg8icFHA.3204@xxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:news:u1bMg8icFHA.3204@xxxxxxxxxxxxxxxxxxxxxxxxxxxx)  
>> Strange problem:  
>> before: Athlon XP 1400 GHz ASUS A7A266 e XP SP1 ou SP2 Ingles + vanilla  
>> 350W power  
>> After: AMD64 3000+ ABIT NF8 XP SP2 PT\_BR + good 350W Seventeen  
>>  
>> both  
>> HD 40 GB Pri Master C:  
>> CD-RW Sec Mas d:  
>> DVD-RW Sec Slave e:  
>>  
>> The problem: My CD-RW is OK, but the DVD-RW have several errors (65  
event  
>> IDs 11 during a failure) and I/O error during copy (in my native  
language:  
>> "O driver detectou um erro de controlador em \Device\CdRom" and "A  
>> solicitação não pôde ser executada devido a um erro do dispositivo de  
E/S"  
>>  
>> I've tried to stop all services, change bios settings, change flat  
cable,  
>> different copy utilities.update drivers, change drives position on  
cables  
>> but...  
>>  
>> certain files can be copied only in SAFE MODE?!?!?!?  
>>  
>> If i try to boot a normal XP system, 70% of the files are copied without  
>> problem, but some files (the same files, ever) have problems in copying.  
>>  
>> But why in safe mode, the problem does not appear?

- >>
- >>
- >>
- > Use the drives in Cable Select with a known good 80 wire 40 pin ribbon
- > cable.
- > Blue = Motherboard
- > Black = Master
- > Gray = Slave
- >
- > Make sure the jumpers on both drives are set to cable select.
- >
- > Most modern motherboards don't really like having the drives set to
- > master/slave using jumpers.
- >
- > Bobby
- >
- >

---

• ***Follow-Ups:***

- ◆ ***Re: DVD-RW after upgrade to AMD64***  
    ◇ *From: Cari \ (MS-MVP\)*
- ◆ ***Re: DVD-RW after upgrade to AMD64***  
    ◇ *From: NoNoBadDog!*

• ***References:***

- ◆ ***DVD-RW after upgrade to AMD64***  
    ◇ *From: Flavio Borup*
- ◆ ***Re: DVD-RW after upgrade to AMD64***  
    ◇ *From: NoNoBadDog!*

- Prev by Date: ***Re: Press F1 to continue***
- Next by Date: ***Re: Deleting IE 6 in XP***
- Previous by thread: ***Re: DVD-RW after upgrade to AMD64***
- Next by thread: ***Re: DVD-RW after upgrade to AMD64***
- Index(es):
  - ◆ ***Date***
  - ◆ ***Thread***