

## Re: Problem Solved – Re: Network Speed

**Source:**

[http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.network\\_web/2004-11/2188.html](http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.network_web/2004-11/2188.html)

---

**From:** Hans-Georg Michna (*hans-georgNoEmailPlease\_at\_michna.com*)

**Date:** 11/19/04

Date: Fri, 19 Nov 2004 11:35:03 +0100

On Wed, 17 Nov 2004 16:34:20 -0500, "Bob S." <junk@nowhere.com>  
wrote:

>Arrrrrggghhhh.....

>

>Hate it when I overlook the simple things...

>

>The 3Com Switch model 610, states it's a 10/100Mb switch right on the front

>label – and it is except the 24 ports are all 10BaseT and there are only 2

>ports which are 100Mb (used for stacking and/or connecting to servers).

>Even changed it out with another router – which I now know also only had

>10Mb ports. Can't make a silk purse out of a sow's ear no-how with old

>hardware. Owner will be updating switch also now along with 4 new

>computers.

>

>I did verify cables, they are "Verified CAT 5" and the pinouts were correct

>for straight-thru cables.

>

>Lesson learned...don't overlook the obvious when it's starring you in the

>face...

Bob,

thanks for reporting back! This is always appreciated. Leads to  
the thing we call experience. (:-)

Hans-Georg

--

No mail, please.