

# WM 6.1 Bluetooth pairing issue

---

*Source:*

<http://www.tech-archive.net/Archive/WindowsCE/microsoft.public.windowsce.app.development/2008-10/msg00056>

---

- *From:* itsmesujesh <[itsmesujesh@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:itsmesujesh@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxx)>
  - *Date:* Thu, 9 Oct 2008 05:26:00 -0700
- 

Hi all,

I have a question:

I have a BPP application(Basic Printing Profile) on Pocket PC and when I try to print on a printer on which pairing is enabled, I am facing some problems in WM 6.1.

On WM 6.0, my application is working fine. But when it comes to WM 6.1, when i get a pass code request from printer, i entered 0000 which is the pass code. But on my WM 6.1 device, a messae was displayed :Device did not connect, Connection failed or incorrect passcode. But actually, pairing does happen and I am able to print. This wrong Messge is causing a problem.

When I try to pair with the printer by trying to "Add Device" from Settings->Connections->Bluetooth->Devices, I am not getting any faulty message.

Pls help me out if possible.

---

Thanks & Regards.  
itsmesujesh

---

Thanks & Regards.

.