

Is this a bug in PB 5.0?

Source:

<http://www.tech-archive.net/Archive/WindowsCE/microsoft.public.windowsce.platbuilder/2004-10/1376.html>

From: Bryan (*anonymous_at_discussions.microsoft.com*)

Date: 10/29/04

Date: Fri, 29 Oct 2004 01:20:15 -0700

Hi all,

I use the PB5.0 to build my firmware.
I added my cec file (include .exe .reg and .bib),
and build/make image.

My .reg can not be added to the reginit.ini.
I have to adjust the project's build order in FileView,
and the .reg file can be added to the reginit.ini.

Is this a bug in PB5.0?

Thanks,

bryan