

USB KITL

Source:

<http://www.tech-archive.net/Archive/WindowsCE/microsoft.public.windowsce.platbuilder/2006-09/msg00575.html>

- *From:* "Pat O" <pdohara@xxxxxxxx>
 - *Date:* 20 Sep 2006 06:35:03 -0700
-

I am attempting to connect to a CE 5.0 image via USB. My ultimate goal is to monitor the performance of this device under network load. So, yes it does have an Ethernet port, but I would rather not use it for sending performance information to my development PC, as I am testing on the Ethernet port. The device is a CPU evaluation board. I am attempting to qualify this CPU for a new product we are working on. The CPU is a 200Mhz ARM processor, that is also responsible for display and network.

When I set my connectivity settings (under target) to Download: Ethernet, Transport: USB, I get the following error when I attempt to connect:

```
(CoreCon) 08:31:44 09/20/2006 Central Daylight Time: Failed to connect the download service
(CoreCon) 08:31:44 09/20/2006 Central Daylight Time: Download service failed to connect
(CoreCon) 08:31:44 09/20/2006 Central Daylight Time: Warning: One or more services failed to connect. Make sure that the service is properly configured.
```

I assume that I need something else running on the CE device, but I am unsure what that is.

<pre>

Tanks for your Support

```
---
/\=== /\=== /\===
<lt;ooo>> <lt;ooo>> <lt;ooo>>
</pre>
```

.