

Question about eTower 633id

Source:

<http://www.tech-archive.net/Archive/Win2000/microsoft.public.win2000.general/2006-08/msg00894.html>

- *From:* cce <cce@xxxxxxx>
 - *Date:* Sun, 20 Aug 2006 09:33:15 GMT
-

I upgraded the OS from Windows ME to Windows 2000 on an eTower 633id. I installed the modem driver available at this Web site: <http://www.priorityonesupport.com/downloads/emachines/> -- the modem is a Conexant (56K ITU V.90 PCI Fax/Modem).

After installing the modem drivers (the modem "shows up), I am left with the following hardware issue: the PCI Simple Communication Controller is showing a configuration problem, that is, no driver.

My question is, where would I get such a driver? I've searched around for it and have had no luck. My impression is that this is a PCI -> MB issue, not a modem issue, per se. If this is not the case, would it make sense just to purchase a new internal modem?

The motherboard for the 633id:

Cognac Micro ATX (ATX V1.2 form factor) motherboard, TriGem, Korea Intel Socket-370 (370pin PPGA Socket) for Intel FC-PGA Celeron CPUs Integrating on-chip Graphics controller and Memory Controller Hub (GMCH): Intel FW82810, as well as Intel I/O Controller Hub (ICH) and AC 97' Controller.

I hope this makes some sense.

Thanks.

.