

Re: misreporting cpu speed

Source:

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.general/2004-11/14630.html>

From: Matt (*Matt_at_discussions.microsoft.com*)

Date: 11/21/04

Date: Sun, 21 Nov 2004 14:25:03 -0800

well i check it out i took my lights and one of my components off the power supply turns out my sound card that also wasnt working came back from my perspective the board actually slow the cpu down a disables components to supply full power i have a 350watt and 3 dvd rom drives a zip 2 hard drives and a floppy 2 lights and 8 fans im pulling way too much power i got the case so long ago i forgot it needed upgraded on the power side thanks for the reply but i think im covering it with the new 700watt im buying

"Jan Alter" wrote:

> *You're sure that the fsb speed is set correctly in the bios?*
>
> --
> *Jan Alter*
> *bearpuf@verizon.net*
> *or*
> *jalter@phila.k12.pa.us*
> *"Matt" <Matt@discussions.microsoft.com> wrote in message*
> *news:64EF2C09-4E23-462C-9CA1-1326F2FF30F8@microsoft.com...*
>> *My custom PC has a AMD Athlon XP 2200+*
>> *Recently it has decided to change to a AMD Athlon 1500+*
>> *I still havent figured out why but it actually is now running at 1.39*
>> *instead of the 1.80 that it had been before*
>> *now i like to overclock this system i built it that way*
>> *but i still haent gott the cpu speed correct with checking my bios for ht*
>> *and to make sure the voltage was average*
>>
>> *anybody think they could help me*
>>
>>
>
>
>