

Re: Sound very low ...

Source:

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.general/2005-11/msg00315.html>

- From: "BJMonty" <BJMonty@xxxxxxxxxxxxxxxxxxxxxxxxxxxxx>
 - Date: Sat, 5 Nov 2005 01:12:07 -0800
-

-----[EVEREST Home Edition (c) 2003-2005 Lavalys, Inc.
]-----

Version EVEREST v2.20.405
Homepage <http://www.lavalys.com/>
Report Type Quick Report
Computer DEFAULTU-E14C65
Generator DefaultUser
Operating System Microsoft Windows XP
Home Edition 5.1.2600 (WinXP Retail)
Date 2005-11-05
Time 19:08

-----[Summary
]-----

Computer:
Operating System Microsoft Windows XP
Home Edition
OS Service Pack Service Pack 2
DirectX 4.09.00.0904
(DirectX 9.0c)
Computer Name DEFAULTU-E14C65
User Name DefaultUser

Motherboard:
CPU Type Intel Pentium IIIE,
1000 MHz (7.5 x 133)
Motherboard Name Dell OptiPlex GX150
Motherboard Chipset Intel Solano i815E
System Memory 253 MB (SDRAM)
BIOS Type Phoenix (11/07/01)
Communication Port Communications Port
(COM1)
Communication Port Communications Port
(COM2)
Communication Port ECP Printer Port

Re: Sound very low ...

(LPT1)

Display:

Video Adapter Intel(R) 82815
Graphics Controller (Microsoft Corporation) (32 MB)
3D Accelerator Intel i752
Monitor Dell P793 [17" CRT]
(4D029188D13W)

Multimedia:

Audio Adapter Intel 82801BA ICH2X
– AC'97 Audio Controller [B–0]

Storage:

IDE Controller Intel(R) 82801BA
Ultra ATA Storage Controller – 244B
Floppy Drive Floppy disk drive
Disk Drive IC35L010AVER07–0
(10 GB, 7200 RPM, Ultra–ATA/100)
Optical Drive Lite–On LTN486S 48x
Max (48x CD–ROM)
SMART Hard Disks Status OK

Partitions:

C: (NTFS) 9530 MB (6093 MB free)

Input:

Keyboard Standard 101/102–Key
or Microsoft Natural PS/2 Keyboard
Mouse PS/2 Compatible Mouse

Network:

Network Adapter 3Com 3C920
Integrated Fast Ethernet Controller (3C905C–TX Compatible)
Network Adapter WAN (PPP/SLIP)
Interface (210.9.116.44)
Modem ESS ES56H–PI Data
Fax Voice Modem

Peripherals:

USB1 Controller Intel 82801BA ICH2X
– USB Controller 1 [B–0]
USB1 Controller Intel 82801BA ICH2X
– USB Controller 2 [B–0]
USB Device CanoScan N650U/N656U

"Brian A." wrote:

> "BJMonty" <BJMonty@xxxxxxxxxxxxxxxxxxxxxxxxxxxx> wrote in message
> news:639C467F-EE22-480E-91B0-2912BEDD4D74@xxxxxxxxxxxxxxxxxxxxx
>> Thanks Brian , I had a look at your links at now im back to explain my

Re: Sound very low ...

Re: Sound very low ...

- >> problem ...
- >> I have plugged it into the correct jack in the desktop and i tried to find
- >> the device manager but i couldnt find it ,
- >
- > Right click MyComputer.
- > Click Properties > Hardware tab > Device manager button.
- >
- > or when in Control Panel double click the System applet.
- > Click Hardware tab > device Manager button.
- >
- >
- > i did try " Does your sound
- >> device show in Control Panel Sounds and Audio Devices Audio tab as the
- >> preferred device? " and it has intel (r) Integrated audio and modem # 1
- >> line playback the first one is selected .
- >
- > I don't know for sure, but intel (r) Integrated audio doesn't seem right.
- > My thoughts at this time is the software for the integrated audio isn't
- > installed.
- > Can you please provide:
- > Computer manufacturer, make/model.
- > Motherboard manufacturer make/model.
- > Chip manufacturer make/model.
- >
- > The best way to get any information needed:
- > Everest Home Edition(Free):
- > <http://www.lavalys.com/products.php?lang=en>
- >
- > Create a new folder named Everest and extract the contents of the download to
- > that folder.
- > Open the folder and double-click everest.exe to run the application.
- >
- > If you are not sure what next step to take, other than downloading/installing
- > from the manufacturers support site.
- > Click the + next to Computer.
- > Click Summary.
- > On the menu bar click Report > Quick Report-Summary > Plain text.
- > Save to your desktop and close Everest.
- >
- > Open the report on the desktop.
- > Delete everything from Debug on down to the bottom of the page and save.
- > Press CTRL+A to select all.
- > Press CTRL+C to copy and close out.
- > Open a response in this thread and press CTRL+V to paste.
- > Post the results in a response to this thread.
- >
- >
- > --
- >
- > Brian A. Sesko { MS MVP_Shell/User }
- > Conflicts start where information lacks.

Re: Sound very low ...

Re: Sound very low ...

> <http://basconotw.mvps.org/>

>

> Suggested posting do's/don'ts: <http://www.dts-l.org/goodpost.htm>

> How to ask a question: <http://support.microsoft.com/kb/555375>

>

>

>

>

.

• **References:**

◆ **Re: Sound very low ...**

◇ *From:* Brian A.

◆ **Re: Sound very low ...**

◇ *From:* Brian A.

• Prev by Date: **Re: Strange Explorer Behaviour**

• Next by Date: **Re: XP Pro-CD writer**

• Previous by thread: **Re: Sound very low ...**

• Next by thread: **Re: System Restore on Windows XP Pro SP2**

• Index(es):

◆ **Date**

◆ **Thread**