

Re: Only one core working

Source:

<http://www.tech-archive.net/Archive/WinXP/microsoft.public.windowsxp.hardware/2006-06/msg00735.html>

- *From:* Jaymon <Jaymon@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxx>
 - *Date:* Fri, 16 Jun 2006 12:49:02 -0700
-

Mick,

Try this, click Start, Run, then type "msconfig" in the run box, click "OK", select the boot.ini tab, advanced options, check the box /NUMPROC= and set = 2, click "OK" and "OK" again to reboot/restart the computer, any change..?

j;-j

"Mick" wrote:

No Joy. Task manager only has one chart showing. Option to show one chart per CPU is greyed out
Bios shows two cores
Device manager shows two processors (working correctly??)
Intel ID shows one processor (one core)
Sisoft Sandra shows one processor (one core)
Premier 2 shows one processor

IS it motheroard or processor fault ??

"Andrew E." <eckrichco@xxxxxxx> wrote in message
news:FD2A5B21-682D-4EAA-91B5-652062B23949@xxxxxxxxxxxxxxxxxxxx

Have you installed the chipset installation utility."Deleted from from device mgr" ,you dont delete,you can uninstall or disable,but delete doesnt get you anywhere...Also,try downloading the hyperthreading chk utility from intel,thiers also,processor identification utility,between the two you should get some accurate results.

"Mick" wrote:

Have Asus P5VD1-X
Win xp Pro SP2 P805 Dual Core
7600GT
2x 512 MB PC 3200

Re: Only one core working

Have lost Dual Core capability, Used to see two graphs in task manager but now only one.
Have updated ASUS Bios to latest 507 , all xp updates.
Bios sees two cores on startup.
2 processors seen in Device manager, which state they are working correctly.
Device shows ACPI multi processor.
Yet only one chart appears on Task Manager graph, function to see one chart per CPU greyed out, and Premiere 2 only sees one processor.
have done full clean install of XP, deleted processors from device manager and redetected, no joy. only one still showing on task manager.
Sisoft sandra and CPUID and intell ID show no errors so where has my 2nd core gone.
If i enable hyperthreading in bios(i know its not a hyperthread proc).
Xp Task manager shows two graph charts and premiere shows multi processor but it crashes.
help.
Mick