

# Re: Clariion CX500

---

*Source:*

<http://www.tech-archive.net/Archive/Windows/microsoft.public.windows.server.clustering/2006-08/msg00044.html>

---

- *From:* "ken\_smith" <[ken@xxxxxxxxxxxxxxxxxxx](mailto:ken@xxxxxxxxxxxxxxxxxxx)>
  - *Date:* 24 Jul 2006 08:34:22 -0700
- 

Default size is 512Kb, you need to change the size when defining the LUN.

You can use Navisphere to Destroy the LUN, then recreate it specifying the sector size you want to use.

John Bell wrote:

Hi Rodney

That was my next step :)

John

"Rodney R. Fournier [MVP]" wrote:

Call EMC and ask them the correct size.

Cheers,

Rodney R. Fournier

MVP – Windows Server – Clustering  
<http://www.nw-america.com> – Clustering Website  
[http://www.ms\\_mvps.com/clustering](http://www.ms_mvps.com/clustering) – Blog  
<http://www.clusterhelp.com> – Cluster Training  
ClusterHelp.com is a Microsoft Certified Gold Partner

"John Bell" <[jbllnewsposts@xxxxxxxxxxxxx](mailto:jbllnewsposts@xxxxxxxxxxxxx)> wrote in message  
[news:481A407D-5555-48E0-9DE3-672A5CD828DB@xxxxxxxxxxxxxxxxxxx](mailto:news:481A407D-5555-48E0-9DE3-672A5CD828DB@xxxxxxxxxxxxxxxxxxx)

Hi

I have just taken over a Windows 2003 SP1 blade server connected to a EMC

Re: Clariion CX500

Clariion CX500. I requested one logical disc to be set up with 8K sectors, which I as assured from the SAN guy had been set up, then someone else configured the server and he has now gone on holiday!

When looking at system info it is saying sector size is 512 bytes. Is this an issue with System Info, is it reporting something else or has it not been set up correctly?

Thanks

John