

eVC debugger problem

Source:

<http://www.tech-archive.net/Archive/WindowsCE/microsoft.public.windowsce.embedded.vc/2007-10/msg00095.htm>

- *From:* "aod" <aod92@xxxxxxxxxxxx>
 - *Date:* Tue, 16 Oct 2007 08:15:31 -0400
-

I have an issue with the debugger, up to a few months ago I could connect to my CE device without any problems to attach to a process and then debug. But now we're getting the error "Toolhelp.dll cannot be copied". This did not happen before. The only change in that sector was that we added the latest QFE to a CE platform but none of them was related to the kernel debugger from what we can see.....
Any idea?

.