

## setFPEmul() missing

---

*Source:*

<http://www.tech-archive.net/Archive/WindowsCE/microsoft.public.windowsce.platbuilder/2008-05/msg00034.html>

---

- *From:* Aplamon <[Aplamon@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx](mailto:Aplamon@xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx)>
  - *Date:* Fri, 2 May 2008 16:10:00 -0700
- 

Hi,

I have migrated our project from CE5.0 to CE6.0 on a ICOP PC104 platform. In 5.0 there was a problem in the init part of the private kernel code that caused the kernel to essentially crash if power was cycled too quickly on the device. We had a fix for it in the private code. I migrated that change to 6.0 and rebuilt the kernel in  
%WINCEROOT%\PRIVATE\WINCEOS\COREOS\NK\KERNEL.  
It built fine but now system build failed due to missing setFPEmul function. I noticed that this was a fairly recent addition in a QFE. Is the private source code out of sync with the provided binaries or?

/Daniel  
.